I - Take Photo

Completed By	[redacted]
Form Version	21
Form Started	Friday 11 Sept 2026 @ 21:00
Form Finished	Friday 11 Sept 2026 @ 21:04
Start Position	[redacted]
Finish Position	[redacted]
Reference	8CD30CDF-93F9-4463-A6E3-FD2161820810
Workforce Individual - Name	[redacted]
Workforce Individual - Contract	456 - Arqiva - UU Smart Metering
Workforce Individual - Area	003 - Arqiva UU Smart Metering - External East
Workforce Individual - Cost Centre	[redacted]

Main

Contract/Area code	456/005-Arqiva UU Smart Metering - External West and North
Agent	[redacted]
Gang	[redacted]
Region	Northwest
Operator Name	[redacted]
Address	[redacted] Bury Road [redacted]

Photos & Comments

Comment	Dug down on outlet of box followed pipe to point to point of entry no leak on pipe or box water coming from the cavity wall plumber on the way to fix this now customer happy leak not on public
Photo	



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery



Source: Gallery